

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

February 10, 1997

TO:

Minerals File

FROM:

Lynn Kunzler, Reclamation Specialist

RE:

Site Inspection, Larson Limestone Quarry, M/049/011, Utah County, Utah

Date of Inspection:

October 1, 1996

Time of Inspection:

9:00 am

Conditions:

clear

Participants:

Mark Hartman, Larson Limestone; Patrick Collins, Mt. Nebo Scientific;

Tony Gallegos, Tom Munson, and Lynn Kunzler, DOGM

Purpose of Inspection: Review site conditions, permit status, and discuss permit deficiencies

We began this inspection with a discussion in the office as to the status of the Division's review of the Notice of Intention. Deficiencies were discussed and explained in more detail. We then took a tour of the Quarry.

Quarry conditions have not changed much since the last inspection. Mr. Hartman indicated that the next 5-10 years, the plan is to deepen the pits, which will create very little new disturbance. This plan will also reduce some of the dump slopes that currently exist. He also indicated that if his company gets the I-15 contract or if the legacy highway gets approval there production could greatly increase.

The need for accurate maps was also discussed. These maps need to show the current disturbance, proposed new disturbance, and those areas that were disturbed and abandoned pre-law (1977). We also discussed bonding requirements briefly, and the types of tasks that would be required for calculating the bond, such a structure removal (including foundations), highwall reduction/stabilization, regrading, ripping, seeding,